


Outdoor Unit



Model	Classification	Description	Part Number	Location Number	Remark
LTUC362NLE0	Cooling	Compressor	TBZ35295901	554160	Barrier Side
		Harness,Multi	6631A20069J	W6631	

Note) * Please ensure GCSC since the replacement parts may be changed depending upon the buyer's request.
 Please check the correct parts in View RPL(Replacement Part List) on GCSC.
 (GCSC Website <http://biz.Lgservice.com>.)

